

Norman H. Bangerter, Governor Dee C. Hansen, Executive Director Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

August 9, 1985

TO:

The Board of Oil, Gas and Mining

THRU:

Lowell P. Braxton, Administrator

FROM:

Susan C. Linner, Reclamation Biologist/Permit Supervisor

RE:

Executive Summary, Western Clay Company, Modification to

Redmond Bentonite Pit permit, ACT/041/012,

Sevier County, Utah

Attached for your information is an Executive Summary for Western Clay Company's Redmond Bentonite Pit. Public notice has been given and the 30-day public comment period will end September 1, 1985.

The Division recommends that you concur with the \$8,300 bond amount, to be held by Division of State Lands and Forestry.

jvb 0060R-33

EXECUTIVE SUMMARY

Mine Name: Redmond Bentonite Pit Operator: Western Clay Company P. O. Box 1067 Aurora, Utah 84620 Telephone: 801-529-3286 Contact Person: Mr. Thomas Chivers	I. D. No.: ACT/041/012 County: Sevier New/Existing: Modification to Existing mine plan Mineral Ownership: State of Utah Surface Ownership: State of Utah Lease No.(s): ML-1937(State)
Life of Mine: 25Years Legal Description: Section 2, Township 21 S.	Permit Term: 5 years
Legal Description: Section 2, Township 21 3.	Nange I west
Mineral(s) to be Mined: Bentonite Mining Methods: Open Pit Acres to be Disturbed: 8.5 Acres Present Land Use: Mining, Grazing Postmining Land Use: Grazing Variances from Reclamation Standards (Rule M-10)	D) Granted: None Requested
Soils and Geology:	
Soil Description: Sandy clay loam - clay, the alluvial fans and low lake terrace, alkaline, pH: Colorado Plateau Province Ave. 8.1-9.1	poorly drained
Special Handling Problems: Extremely high so Geology Description: Bentonite is found in vi	pleanics pear Redmond. High Plateaus
dissected by main drainages. Local folding ca	using steep dipping in stratified
formations and giving rise to hogbacks.	
Hydrology:	
Ground Water Description:	N/A
Surface Water Description: Runoff from the a	rea resulting from the 8 inches of
annual precipitation could enter the Piute Can All drainage from the disturbed area is contai	at and eventually the Sevier River.
evaporates.	Hed locally in pits and ponds where it
Water Monitoring Plan: N/A	

Page 2 Executive Summary ACT/041/012

Ecology:

Vegetation Type(s); Dominant Species: Salt Desert Shrub, Shadsacle, Snakeweed, Sand dropseed, Indian Ricegrass
Percent Surrounding Vegetative Cover: 15% Wildlife Concerns: None. Area is considered to have been overgrazed. Surface Facilities: Open pit and ponds. All raw product is hauled to Aurora for processing.
Mining and Reclamation Plan Summary: Test plots are in place to determine the most feasible techniques. Fencing has been/will be done to mitigate safety hazard. See attached.
Surety:
Amount:\$8,300 Form: Renewable Term: _5years (1990 dollars)

0352R-7

OPERATION AND RECLAMATION PLAN

During Operations:

- 1. The bentonite clay deposit being mined occurs on the surface and thus does not require explosives to mine. It sometimes requires ripping. The clay is mined with a front-end loader and loaded into a truck for transport to a processing plant in Aurora, Utah
- 2. There will be no structures on site.
- 3. Any topsoil or overburden present will be removed for reclamation purposes.
- 4. Runoff from the minesite will be contained in two catch basins. Any water collecting in the pit will be pumped so as to flow into the catch basins.

Following operations:

- 1. All trash and debris will be cleaned up.
- 2. Slopes will be regraded to a stable configuration.
- 3. Soil material will be reapplied, harrowed and drill seeded with a mixture adapted to the area.
- 4. Test plots have been implemented to help determine the best methods for successful reclamation.